



**MONUMENT RECORD**  
**State of Indiana - County of Monroe**

**Section: 20**

**Township: 8 North**

**Range: 1 West**


**Corner ID: Per G-17**

**Monument Description & Remarks:** Found Railroad Spike (point A) in centerline of Church Lane at South 1/4 corner of section, 22.51' west of second railroad spike in centerline (point E) erroneously referenced as corner by William Bateman, R.L.S. in 1883. Monument is in line with property boundary on north/south line. **References on file in the County Surveyor's Office:** "May Boundary" survey prepared by Smith Quillman, dated May, 1991. Mundy survey dated September, 1997, Book 4, Page 345, Recorder's

**RECOVERY TIE DRAWING**

Field Book 98-01 Page No. 19 (Reference Field Book 97-02, Page No. 68)

USGS Clear Creek Quad



- A - Railroad Spike
- B - North 15 degrees West, 17.61' from corner  
PK nail in 18" Sugar Maple
- C - North 75 degrees East, 39.10' from corner  
PK nail in 21" Black Cherry
- D - South 77 degrees East, 99.80' from corner  
PK nail in 24" concrete pole
- E - South 86 degrees East, 22.51' from corner  
Railroad Spike in centerline Church Lane

Not To Scale

Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code and the above data is given under my hand and seal this 8th day of January, 1998.



Administered by: Surveyor Review Board



MONUMENT RECORD


STATE OF INDIANA - COUNTY OF MONROE

SECTION 29, TOWNSHIP 8 NORTH, RANGE 1 WEST

MONUMENT DESCRIPTION & REMARKS

RAILROAD SPIKE SET IN CENTERLINE OF CHURCH LANE BY WILLIAM  
BATEMAN R.L.S. # 12056 CORNER TIE INFORMATION ALSO FROM  
MR. BATEMAN TIES CHECKED BY MICHAEL FRILEY

RECOVERY TIE DRAWING



STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 25 TH DAY OF AUGUST, 1983 A.D.

SPACE RESERVED FOR RECORDING OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP: PERRY

CORNER I.D.

TITLE

This Corner Reference is incorrect See tie sheet dated 1-8-92

Job # 83-46

74

Aug. 10, 1983  
500 88  
K.P.  
CLEAR 90°

P.K. IN 24"  
MAPLE

set R.R. SPR @  
N.E. Cor at N.W 1/4  
SEC 29 T-8-N R-1-W  
MONROE Co.

P.K. IN 30"  
WOOD CHERRY

APPROX  
CHURCH LANE

32.44'

19.38'

44.45'

26.52'

STONE WALL

Fence

P.K. IN wood  
Fence POST

P.K. IN  
wood Fence POST

CERTIFIED CORRECT  
William D Bateman  
WILLIAM D BATEMAN  
RLS #12056